

L Number	Hits	Search Text	DB	Time stamp
1	35	"3R regenerator"	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/08/19 10:23
2	18	"3R regenerator" and clock	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/08/19 10:23
3	12	("3R regenerator" and clock) and delay	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/08/19 13:06
4	0	rehenerat\$4 same clock same (delay adj interference)	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/08/19 10:35
5	5	regenerat\$4 same clock same (delay adj interference)	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/08/19 10:35
6	6	("5781326" "5940207" "5959764" "6259552" "6335819" "6377388").PN.	USPAT	2003/08/19 10:50
7	3	6335819.URPN.	USPAT	2003/08/19 10:53
8	8	("5532861" "5726787" "5959764" "5974209" "6101027" "6108125" "6124966" "6215566").PN.	USPAT	2003/08/19 10:57
9	4	("5761228" "5796765" "5799024" "5844932").PN.	USPAT	2003/08/19 11:02
10	1	6124966.URPN.	USPAT	2003/08/19 11:53
11	10	6108125.URPN.	USPAT	2003/08/19 11:57
12	5	("5401957" "5548433" "5717510" "5757529" "5892608").PN.	USPAT	2003/08/19 11:57
13	8	("5532861" "5726787" "5959764" "5974209" "6101027" "6108125" "6124966" "6215566").PN.	USPAT	2003/08/19 12:04
14	3	6335819.URPN.	USPAT	2003/08/19 12:04
15	6	("5111326" "5267073" "5619368" "5625479" "5828484" "5960146").PN.	USPAT	2003/08/19 12:10
16	1	6259552.URPN.	USPAT	2003/08/19 12:11
17	7	5781326.URPN.	USPAT	2003/08/19 12:14
18	3	6229633.URPN.	USPAT	2003/08/19 12:32
19	19	("4881788" "5150248" "5369520" "5369522" "5379143" "5434692" "5444560" "5446573" "5450229" "5504610" "5515199" "5546190" "5548433" "5574588" "5644665" "5774246" "5781326" "5822103" "6067180").PN.	USPAT	2003/08/19 12:33
20	9	5574588.URPN.	USPAT	2003/08/19 12:40
21	1	"5457559".PN.	USPAT	2003/08/19 12:46
22	13	5457559.URPN.	USPAT	2003/08/19 12:48
23	19	("4881788" "5150248" "5369520" "5369522" "5379143" "5434692" "5444560" "5446573" "5450229" "5504610" "5515199" "5546190" "5548433" "5574588" "5644665" "5774246" "5781326" "5822103" "6067180").PN.	USPAT	2003/08/19 12:55
24	3	6229633.URPN.	USPAT	2003/08/19 12:55
25	116	359/176 and delay	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/08/19 13:06
26	71	(359/176 and delay) and clock	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/08/19 15:20

27	13	("5237290" "5416769" "5469284" "5486943" "5734486" "5737106" "5757872" "5831752" "5999293" "6067180" "6091524" "6282007" "6373608").PN.	USPAT	2003/08/19 13:53
28	3	("5401957" "5594583" "5625636").PN.	USPAT	2003/08/19 14:33
29	5	5401957.URPN.	USPAT	2003/08/19 14:34
30	2	5861971.URPN.	USPAT	2003/08/19 14:35
31	4	5764396.URPN.	USPAT	2003/08/19 14:45
32	8	("4350879" "4561101" "5369520" "5392147" "5459607" "5493433" "5548433" "5646759").PN.	USPAT	2003/08/19 14:46
33	135	359/176 and clock	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/08/19 15:33
34	113	"optical regenerator" and clock	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/08/19 15:34
35	11	("4313224" "5107483" "5410624" "5483372" "5532863" "5539557" "5576883" "5689594" "5777766" "5801862" "5838475").PN.	USPAT	2003/08/19 15:39
36	15	4980891.URPN.	USPAT	2003/08/19 15:48